Amendments to the Drawings:

The originally-filed drawings were informal drawings. The attached sheets provide formal drawings to replace the informal drawings, i.e., for Figures 1-13. No new matter is added, and hence, no annotated sheets showing changes are provided or necessary.

Appl. No. 09/635,823
Amdt. Dated January 14, 2004
Reply to Office Action of December 23, 2003
Replacement Sheet

1/13

FIG.1

Appl. No. 09/635,823
Amdt. Dated January 14, 2004
Reply to Office Action of December 23, 2003
Replacement Sheet

2/13

FIG.2

Appl. No. 09/635,823
Amdt. Dated January 14, 2004
Reply to Office Action of December 23, 2003
Replacement Sheet

3/13

ADMINISTRATOR REGISTRY

FILE EDIT VIEW FAVORITES TOOLS HELP

BACK FORWARD STOP REFRESH HOME | SEARCH FAVORITES HISTORY | MAIL PRINT EDIT MESSENGER

ADDRESS http://129.155.8.69:8080/webscout/listadmin

LINKS @BEST OF THE WEB @CHANNEL GUIDE @CUSTOMIZE LINKS @FREE HOTMAIL @INTERNET START @MICROSOFT @WINDOWS UPDATE @WINDOWS

My Sun|Regional Sites|Site Index|How To Buy

sun.com

SELECT A TOPIC ▾ Go

Home > Sun Environment Insight Manager > Administrator Registry

Sun Environment Insight Manager

-Create Account
-Administrator Registry
-Search Company

Administrator Registry

Related:
-Data Sheets
-White Papers
-Free Solaris Promotion for Non-Commercial Use

List of all administrators for all companies

Company	Department	First Name	Last Name	Email	Phone	Fax
DHC,Inc.	DHC, Inc.	Mary	Greenspan	marygreenspan@dhm.com	857-4559585	234-5476764
NEC	NEC	NEC Demo	Lastname	support@nec.com	1-800-NEC-1234	1-800-NEC-FAX1
SUN	ENGINEERING	John	Smith	john.smith@sun.com	123-1231221	132-2132131
SUN	HARDWARE	Mark	Half	mark.half@compaq.com	576-4564344	785-5721647
SUN	HARDWARE	John	Smith	john.smith@sun.com	123-1231221	132-2132131
SUN	HUMAN RESOURCE	Mary	Greenspan	marygreenspan@dhm.com	857-4559585	234-5476764
SUN	QUALITY ASSURANCE	John	Smith	john.smith@sun.com	123-1231221	132-2132131

See Also:
-Solaris Operating Environment
-Documentation
-Solaris Intel Spotlight
-Solaris System
-Partners
-Solaris Developer Connection
-Software Subscriptions
-Year 2000

Solaris 8 Adoption Services: Readiness Evaluations|Application Fitness Services|Sun Migration Services|Implementation Services|Enrichment Services|Tools|ISV Status|Freeware Status|Other
Links of Interest|Order Services

Search

FIG.3

Appl. No. 09/635,823
Amdt. Dated January 14, 2004
Reply to Office Action of December 23, 2003
Replacement Sheet

4/13

FIG.4

Appl. No: 09/635,823
Amdt. Dated January 14, 2004
Reply to Office Action of December 23, 2003
Replacement Sheet

5/13

FIG.5

Appl. No. 09/635,823
Amdt. Dated January 14, 2004
Reply to Office Action of December 23, 2003
Replacement Sheet

6/13

FIG.6

Appl. No. 09/635,823
Amdt. Dated January 14, 2004
Reply to Office Action of December 23, 2003
Replacement Sheet

7/13

FIG.7

FILE EDIT VIEW GO COMMUNICATOR HELP

BACK | FORWARD | RELOAD | HOME | SEARCH | NETSCAPE | PRINT | SECURITY | SHOP | STOP

BOOKMARKS LOCATION: http://216.183.9.125/webscout/noncompsys

INSTANT MESSAGE | WEBMAIL | RADIO | PEOPLE | YELLOW PAGES | DOWNLOAD | CALENDAR | CHANNELS | WHAT'S RELATED

N

sun.com

My Sun|Regional Sites|Site Index|How To Buy

Search

SELECT A TOPIC ▷ Go

Home >WebScout Administration >SUN/ENGINEERING >Solaris 8 Compliance Reports
>Non-Compliant Systems

204

-Compliant Systems
-Non-Compliant Systems
-Model Summary
-Solaris Version Compliance
-Non-Compliant Binaries Location
-Completed Surveys
-Search Binary
-WebScout Logout

Related:
-Data Sheets
-White Papers
-Free Solaris Promotion for Non-Commercial Use

See Also:
-Solaris Operating Environment
-Documentation
-Solaris Intel Spotlight
-Solaris System Partners
-Solaris Developer Connection
-Software

Solaris 8 Compliance Reports

Non-Compliant Systems

Name	Model	Solaris	Binaries	Insufficient Memory	Insufficient Arch. Disk Space	Last Surveyed
abyss	Ultra-60	5.7	5			01-11-2000 17:04:44
deanna	Ultra-1	5.6	13	YES		02-09-2000 16:33:57
ludo	Ultra-1	5.8	38			02-09-2000 16:33:57
stargate	Ultra-5_10	5.7	6			01-11-2000 04:27:11
turtle	Ultra-1	5.7	6			02-09-2000 16:33:57
wildcat	Ultra-2	5.8	107			02-09-2000 16:33:57

242

240

Appl. No. 09/635,823
Amdt. Dated January 14, 2004
Reply to Office Action of December 23, 2003
Replacement Sheet

8/13

FIG.8

Appl. No. 09/635,823
Amdt. Dated January 14, 2004
Reply to Office Action of December 23, 2003
Replacement Sheet

9/13

Java Scout

File

Machine List Tree
Machine List
cheerio (1)
procyon (1)
stargate (1)
explorer (1)
hp6mp (1)
mobile (1)
rocket (1)
solar (1)
soltest (1)

302

Current Machine: Cheerio, 1999-11-24 18:25:26

306

System Information Tree
System Inventory tree
System (SunOS cheeri
Hardware
CPU (1 processor)
Memory (384MB)
Network (hme0)
Hard Disk (3 hard
Floppy disk (diske
CDROM (IDE. c0t2d0
Graphics card (m64
Parallel ports (1
Serial ports (2 po
EEPROM (paramete
Software
Y2K Compliance
System Configuration
Kernel Configuration
System Status

304

Detailed Reports

Size of memory modules:

hostname: cheerio
banner: Sun Ultra 5/10 UPA/PCI (UltraSPARC - II1 27 OM
model: Ultra-5_10
socket DIMM1 has a 128 MB DIMM (bank 0L, address 0x000
socket DIMM2 has a 128 MB DIMM (bank 0H, address 0x000
socket DIMM3 has a 64 MB DIMM (bank 1L, address 0x2000
socket DIMM4 hsa a 64 MB DIMM (bank 1H, address 0x2000
total memory = 384 MB

Status & Recommended Actions

Sizes of SIMM/DIMM memory modules

FIG.9

Appl. No. 09/635,823
Amdt. Dated January 14, 2004
Reply to Office Action of December 23, 2003
Replacement Sheet

10/13

Java Scout

File

Machine List Tree
Machine List
  cheerio (1)
  procyon (1)
  stargate (1)
  explorer (1)
  hp6mp (1)
  mobile (1)
  rocket (1)
  solar (1)
  soltest (1)

Current Machine: Cheerio, 1999-11-24 18:25:26

System Information Tree
System Inventory tree
  System (SunOS cheeri
    Hardware
      CPU (1 processor)
      Memory (384MB)
      Network (hme0)
      Hard Disk (3 hard
      Floppy disk (diske
      CDROM (IDE. c0t2d0
      Graphics card (m64
      Parallel ports (1
      Serial ports (2 po
      EEPROM (paramete
    Software
      Packages (total 37
      Patches (total 88
        Installed Patche
        Recommended Patc
      Y2K Compliance
      System Configuration
      Kernel Configuration
      System Status

Detailed Reports

Recommended Patches (48 patches) currently

Notes

Recommended patches are considered the most impor
recommended patches that avoid the most critical
security related bugs which have been reported ar

	Patch ID	Ins Rev	Lat Rev	Age	Require I.D.	Incomp I.D.	Synopsis
1:	105390	N/A	02	632			SunOS 5.
2:	105395	N/A	06	162			SunOS 5.
3:	105591	N/A	06	226			SunOS 5.
4:	105665	N/A	03	441			SunOS 5.
5:	105926	N/A	01	670			SunOS 5.
6:	106029	N/A	03	236			SunOS 5.
7:	106040	N/A	11	124			SunOS 5.
8:	106049	N/A	01	544			SunOS 5.
9:	106123	N/A	04	324			SunOS 5.
10:	106193	N/A	03	446			SunOS 5.
11:	106226	N/A	01	540			SunOS 5.
12:	106235	N/A	03	250			SunOS 5.
13:	106257	N/A	04	488			SunOS 5.
14:	106271	N/A	05	309			SunOS 5.
15:	106301	N/A	01	568			SunOS 5.
16:	106439	N/A	04	453			SunOS 5.
17:	106448	N/A	01	498			SunOS 5.
18:	106495	N/A	01	519			SunOS 5.
19:	106504	N/A	01	498			SunOS 5.

Status & Recommended Actions

Information about uninstalled patches.
Recommended patches are considered the most important and highly

FIG.10

Appl. No. 09/635,823
Amdt. Dated January 14, 2004
Reply to Office Action of December 23, 2003
Replacement Sheet

11/13

FIG.11

Appl. No. 09/635,823
Amdt. Dated January 14, 2004
Reply to Office Action of December 23, 2003
Replacement Sheet

12/13

FIG.12

Appl. No. 09/635,823
Amdt. Dated January 14, 2004
Reply to Office Action of December 23, 2003
Replacement Sheet

13/13

FIG.13